

100-09C

STAT




21 August 1951
22-574

Electrical Work — South Building

It is kindly requested that the necessary arrangements be made to have the bumper system located between Rooms 307, 317A, 317, 321, 349 and 355 South Building renovated to conform with the attached sketch.

Due to certain structural changes made in this area, these renovations are required and should be completed as soon as possible.

STAT



may be contacted for pertinent details.

Charge to our order no. 440.

*Work completed
14 Oct 72 51*